



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
October 11, 2005

Supervisor *DRH*

Mine Name: Red Sandstone Quarry
Operator Name: Ron Stout
900 Industrial Road
P.O. Box 251
St. George, Utah 84770

Permit number: S/053/073
Inspection Date: Sept. 28, 2005
Time: 6:00 PM

Inspector(s): Doug Jensen
Other Participants: None
Mine Status: Active

Weather: Warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

While in the area, I stopped to check the progress of mining at the site.

Inspection Summary:

The site is active and the operator has continued to remove material from the site. Mining at the site appears to be going slowly. The site has not changed much since my last visit in 2003.

Conclusions and Recommendations:

I will continue to monitor this site when I am in the area.

Inspector's Signature *Doug Jensen*

Date: October 11, 2005

dj:jb

cc: Ron Stout, Operator
John Blake, SITLA

O:\M053-Washington\S0530073-RedSandstone\Inspections\insp-09282005.doc